

Splice Damage Detection—Example

Complete Conveyor
Solutions...

Contact Details:

Peter Thorpe
General Manager
Mob: 0410 649 256
peter.thorpe@rescan.com.au

Ben Cole
QLD Manager
Mob: 0408 705 648
paul.harris@rescan.com.au

Tony Moreland
NSW Manager
Mob: 0408 597 087
Tony.Moreland@rescan.com.au


James Warbrick
WA Manager
Mob: 0407 544 497
james.warbrick@rescan.com.au



RESCAN

Unit 1,14 Accolade St
Morisset NSW 2264
Australia

Phone: +61 2 4973 2399
Fax: +61 2 4970 4061
Email: info@rescan.com.au



Above is shown a magnetic splice signature for one splice in February and in March. A change to an area in the leading left of the splice was noted during the March scan. Onsite inspections revealed that two cords had looped out of the splice and had broken whilst a third cord was damaged. Repairs were able to be quickly made to